

## Errata to ICC/ANSI A117.1-2003, Second Printing

Page vi, second paragraph: line 3 now reads . . . ance with the provisions of ICC A117.1-2003. ICC does not have the power or

Page ix, Interest Category totals:, Professional **-(P)** now reads . . . 13

Page ix, Interest Category totals:, Total now reads . . . 43

Page 2, Fig. 104.2 now reads . . . 104.3

Page 7, Fig. 302.2 revised as shown.

Page 16, Fig. 403.5.1 (a) revised as shown.

Page 54, Section 607.4: Exception 2, line 3 now reads . . . plying with Section 1003.11.4 is installed

Page 57, Fig. 608.2.1 revised as shown.

Page 58, Section 608.3: Exception 2, line 3 now reads . . . plying with Section 1003.11.4 is installed

Page 59, Section 608.4: Exception 2, line 3 now reads . . . ment complying with Section 1003.11.4 is

Page 90, Section 1003.3.2: Exception now reads . . . **EXCEPTION:** Toilet rooms and bathrooms that are not required to comply with Sections 1003.11.5 through 1003.11.9.

Page 91, Section 1003.11.1: line 2 now reads . . . shall comply with Section 1003.11.4. At least one

Page 95, Fig. 1003.12.4 revised as shown.

## Errata to ICC/ANSI A117.1-2003, Third Printing

Page 41, Section 504.8.1: line 1 now reads . . . 504.8.1 Illumination Level. Lighting facilities

Page 41, Section 504.8.1: line 3 now reads . . . (108 lux) of illuminance measured at the center

Page 41, Section 504.8.2: line 3 now reads . . . the stairway lighting so the illuminance level

Page 44, Section 506: new section added now reads . . . **506.1 General.** Accessible windows shall have operable parts complying with Section 309.

Page 51, Fig. 604.8.5 revised as shown.

Page 79, Table 802.10: column 2, row 1 now reads . . . Minimum required number of dispersed locations

## Errata to ICC/ANSI A117.1-2003, Fourth Printing

Page 18, Fig. 404.2.3.1(a) revised as shown.

Page 20, Fig. 404.2.3.4(a) revised as shown.

Page 26, Fig. 407.2.1.1 revised as shown.

Page 30, Table 407.4.1: table title now reads . . . Table 407.4.1—Minimum Dimensions of Elevator Cars

Page 68 Fig. 703.4.3 revised as shown.

## Errata to ICC/ANSI A117.1-2003, Eighth Printing

Page 7, Section 303.4: line 1 now reads . . . 303.4 Ramped. Changes in level greater than  $\frac{1}{2}$

